

#	Reported Date	Work Order Description	Nature of breakdown	Time out of service
1	29/11/2017 09:15	FULL RESET FOR LIFT - H10 LIFT EXTERNAL COPPERBOX LIFT.	Clamp on door best broken	6 days
2	12/12/2017 08:36	Wallis Bridge/ H10 lift in not operational	Safety edge timed out	8 hours
3	30/01/2018 10:19	H10 lift - Investigate as lift is out of order	door lock fault	3 hours
4	28/02/2018 14:25	Parklands - Investigate H10 Lift out of service	Door lock fault	1 day
5	19/03/2018 12:07	Wallis Bridge H10 lift - lift out of order and the upper level lift door can t be shut	Door lock fault	2 hours
6	29/05/2018 11:21	H10 Lift - Investigate lift as out of service	Passenger misuse	1 day
7	04/06/2018 10:17	H10 lift out of service	Car gate fault	14 days
8	20/06/2018 08:25	H10 Lift - Out of service	Working on arrival	Working on arrival
9	21/06/2018 08:00	H10 - Non operational - from DFR report	unknown	unknown
10	20/08/2018 08:29	H10 Lift - out of service	unknown	unknown
11	30/08/2018 11:18	H10 lift not working	unknown	2 hours
12	12/09/2018 09:50	H10 Lift - 2 people trapped in the lift	Passenger misuse	2 hours
13	03/10/2018 09:30	North Parklands - H10 Lift - Out of action	unknown	1 hour
14	04/04/2019 09:32	H10 Lift out of operation	Passenger misuse	4 hours
15	23/04/2019 08:50	H10 lift not operational	Contactort fault	1 day
16	09/05/2019 08:22	H10 Lift out of service	Multiple faults	Refer to #17
17	13/05/2019 08:41	H10 - H10 lift out of service.	Multiple faults	8 days (Continuation from #16)
18	21/05/2019 08:13	H10 Lift not operational	Passenger misuse	4 hours
19	20/07/2019 00:59	North Parklands - H10 Lift - Lift has stopped working	Door lock fault	13 days
20	27/08/2019 08:19	H10 Lift not in service	Failed PCB	13 days
21	01/11/2019 19:00	CBA - H10 Lift - Lift Not working	Lift reset	22 mins
22	06/11/2019 09:12	H10 Lift - not working	Door lock fault	3 hours
23	07/11/2019 07:00	H10 Lift not in service	unknown	7 days
24	25/11/2019 08:12	H10 Lift out of service	Door misaligned	8 hours
25	08/04/2020 03:27	CBA - H10 Lift - Out of Service	Car door misaligned	
26	09/07/2020 06:15	H10 Lift - Is currently out of order	Door operator drive belt clamp fixing sheared	9 hours
27	13/07/2020 07:02	H10 Lift out of service	Safety Edge fault	10 hours
28	29/07/2020 07:05	H10 Lift - is stuck on the top level with the doors open	Safety edge fault	Unknown
29	25/08/2020 13:11	H10 Lift is not working	New button required	Unknown
30	04/11/2020 18:30	CBA - H10 Lift - Ceased Operating - reported OOH	Proximity/Inductor fault	22 hours
31	06/11/2020 13:08	CBA - H10 Lift - Ceased Operating	Safety line fault	2.5 hours
32	27/11/2020 11:46	CBA - H10 Lift - Report to be currently out of service.	Door closer air cord & counterweight	Refer to #33
33	03/12/2020 12:24	CBA - H10 Lift - Report to be currently out of service. - Further works to place as quoted on RQ1688	Door closer air cord & counterweight	24 days (continuation from #32)
34	30/12/2020 10:05	QEOP - North side - H10 - Lift is out of service, can an engineer please check.	Lift reset	4 hours
35	28/01/2021 11:04	H10 Lift - issues with the ground floor landing door.	Door fault	Unknown

36	05/02/2021 15:11	CBA - H10 Lift - Wallis bridge not working correctly as the door on bridge level keep opening and cl	Door lock fault	3 hours
37	06/02/2021 20:50	H10 Lift out of service	Hydraulic Unit failed	#38
38	01/03/2021 16:23	H10 - External Lift - Replacement Faulty Driver is required	Faulty driver	7 days
39	10/03/2021 15:21	CBA - External - H10 Lift - Reports of the lift been out of service	Fault on circuit board	2 days
40	09/05/2021 21:29	CBA - H10 External Lift - Reports of been Out Of Service	Doors out of alignment	13 hours
41	18/05/2021 21:30	OOH - CBA - H10 Lift - Lift not working - Liftec Reference LT1305	Doors out of alignment	12 hours
42	31/05/2021 14:03	CBA - H10 Lift - Lift has grounded and is out of service	Door lock fault	5.5 hours
43	07/06/2021 09:38	CBA - H10 lift - Not operational	N/A	Lift found in service
44	17/07/2021 16:08	OOH - H10 Lift -has stopped working,	Working on arrival	Working on arrival
45	20/07/2021 08:39	H10 - Lift out of Service	Door lock fault	3 hours
46	08/11/2021 09:54	H10 - Lift - Reports of the Lift been out of Service - please can you confirm the status of the lift	Failure to start fault	9 days
47	30/11/2021 17:46	H10 - Lift is currently out of service	Lock fault & door closer aircord	7 days
48	02/02/2022 23:02	South Parklands - H10 External Lift - Reports of been out of service - Logged with Liftec under Ref	Multiple faults	10 hours
49	07/02/2022 09:44	North Parklands - H10 External Lift - Reports of been out of service	Safety line broken fault	7 hours
50	01/03/2022 09:00	CBA - H10 - Lift entrapment	Door operator fault	Still out of service